

Faggildingarnúmer: **43**  
 Accreditation number:

Dagsetning: Date:	20.12.2019	Tilvísunarnúmer: Reference number:	201906-5285
----------------------	------------	---------------------------------------	-------------

**1 Almennar upplýsingar / General information**

Kröfur vegna faggildingar koma fram í eftirfarandi skjölum:

Requirements for the accreditation are in the following documents:

Lög nr. 24/2006 um faggildingu o.fl.	Laws no. 24/2006 on accreditation etc.
Reglugerð nr. 346/1993 um starfsemi faggiltra óháðra skoðunarstofa	Regulation no. 346/1993 on the activities of accredited independent inspection bodies
Reglugerð 8/2009 um skoðun ökutækja	Regulation 8/2009 on inspection of vehicles
ÍST EN ISO/IEC 17020:2012	ÍST EN ISO/IEC 17020:2012
Skoðunarhandbók ökutækja frá Samgöngustofu	The Vehicle Inspection Manual from the Icelandic Transport Authority

**2 Aðrar upplýsingar / Other information**

**2.1 Samræmismatsstofa / Conformity Assessment Body**

Betri skoðun ehf.

Kennitala / ID no: 540794-2199

betriskodun@betriskodun.is

**2.2 Lykilstarfsfólk / Key personnel**

Tæknilegur stjórnandi / Technical manager: Hörður Harðarson

Gæðastjóri / Quality manager: Reynir Þrastarson

**2.3 Aðsetur aðalskrifstofu / Head office address**

Stapahraun 1  
 220 Hafnarfjörður  
 Iceland

**2.4 Útibú samræmismatsstofu / Branches of Conformity Assessment Body**

Faggilt samræmismat fer fram á eftirtöldum stöðum:

Accredited Conformity Assessment is performed in the following locations:

Útibú Branch	Staðsetning Location	Skoðar eftirfarandi: Inspects the following:
120	Stapahraun 1 220 Hafnarfjörður Aðalskrifstofa / Head Office	Bifreiðar að 7.500 kg og eftirvagnar að 3.500 kg heildarþyngd, án lofthemla; bifhjól; hjólhýsi; tjaldvagn.  Vehicles up to 7.500 kg and trailers up to 4.000 kg total weight, without airbrakes; motorcycles; caravans; camping trailer.

Endir  
 End